



# Pre-Shipment Inspection Certificate

1. We hereby declare that the second-hand motor vehicle described hereunder, to be exported to Plurinational State of Bolivia/already imported into Plurinational State of Bolivia has been inspected by our organization. The particulars of the inspection are specified hereunder and this Pre-shipment Inspection Certificate/Inspection Certificate\* has been issued to the under-mentioned applicant.

- (a) Name of Inspection Organization EAA Company Limited
- (b) Address 1-20-5-101 Rinkan, Yamato-shi, Kanagawa-ken, Japan
- (c) Tel No. 046-205-7611 Fax No. 046-205-7610 E-mail. info@eaa-s.jp
- (d) Place of Inspection Yokohama
- (e) Date of Inspection 2022/02/17



## 2.Particulars of application:

- (a) Name ROSPER INTERNATIONAL
- (b) Address 2-8-21-218 Tsuruma, Yamato Shi, Kanagawa Ken
- (c) Tel No. +819022308435 Fax No. +81462057610 E-mail; info@rosper.co.jp

## 3.Particulars of second-hand motor vehicle

(1) Type of Vehicle	<u>Station Wagon</u>
(2) Make	<u>TOYOTA</u>
(3) Model	<u>5BA-NSP170G</u>
(4) Commonly Called (emblem reading)	<u>SIENTA</u>
(5) Grade (emblem reading)	<u>G CUERO</u>
(6) Body Color	<u>Blue</u>
(7) Fuel Type	<u>GASOLINE</u>
(8) Year of Manufacture	<u>2020</u>
(9) Year/Month of First Registration	<u>2020/07</u>
(10) Inspection Mileage (odometer reading)	<u>3,217 km</u>
(11) Engine Capacity	<u>1,490 cc</u>
(12) Chassis Number	<u>NSP170-7256696</u>
(13) Engine Number	<u>1199742</u>
(14) Unladen Weight	<u>1,320 kg</u>
(15) Gross Vehicle Mass	<u>1,705 kg</u>

The vehicle is manufactured with less than or equal to value of following JAPANS Standard.  
JAPAN Standard JC08H+JC08C(g/km)

CO 1.15 g/km      NMHC 0.05 g/km      Nox 0.025 g/km      PM - g/km

## 4.We hereby certify and confirm –

- (a) having cross-checked with the Vehicle Registration Authority the original of the last document emanating thereof and having inserted our seal as hereunder on both sides of the document;
- (b) that the vehicle as described above is roadworthy and usable;
- (c) that the vehicle not been stolen;

Remarks We certify that the following vehicles are not damaged by water and not have radiation above 0.3µSv/h.

Certification Number; VE-2202-002-001

Date of Issue; 2022/02/17

Seal of organisation



Signature Prosper Sugal  
Name; Prosper Sugal  
Designation; Director



# EAA COMPANY LIMITED





# Vehicle Inspection Sheet 1

TYPE OF VEHICLE	DRIVING SYSTEM	WEATHER CONDITION
Sedan Car <input type="checkbox"/>	FF <input checked="" type="checkbox"/>	GOOD <input checked="" type="checkbox"/>
Station Wagon <input checked="" type="checkbox"/>	FR <input type="checkbox"/>	DARKNESS <input type="checkbox"/>
Van <input type="checkbox"/>	2WD <input checked="" type="checkbox"/>	RAINY <input type="checkbox"/>
Truck <input type="checkbox"/>	4WD Full Time <input type="checkbox"/>	
Jeep style <input type="checkbox"/>	4WD Part Time <input type="checkbox"/>	
Double Cab Truck <input type="checkbox"/>		
Bus ( Seaters) <input type="checkbox"/>		


WHETHER BODY ACCIDENTED	*ALTERATION OF VEHICLE	CRACK OF WINDSCREEN
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>

\*To confirm whether the vehicle was reconditioned after having been damaged by accident or by natural calamities, including flood.

<b>BODY COLOR:</b>	Blue <input type="checkbox"/>	Normal <input checked="" type="checkbox"/>	Metallic <input type="checkbox"/>	2-Tone Colour <input type="checkbox"/>
--------------------	-------------------------------	--	-----------------------------------	--

TRANSMISSION	NUMBER OF DOORS	TYPE OF ROOF
FLOOR <input type="checkbox"/> A/T <input checked="" type="checkbox"/>	2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input checked="" type="checkbox"/> 6 <input type="checkbox"/>	HIGHT <input type="checkbox"/>
COLUMN <input checked="" type="checkbox"/> M/T <input type="checkbox"/>		MEDIUM <input type="checkbox"/>
3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6~ <input type="checkbox"/>		STANDARD <input checked="" type="checkbox"/>

SHAPE AND BODY OF TRUCK	
Wide <input type="checkbox"/> Cab <input type="checkbox"/> Bonnet <input type="checkbox"/> Standard <input type="checkbox"/> Long <input type="checkbox"/> Super Low Deck <input type="checkbox"/> Low Deck <input type="checkbox"/> High Deck <input type="checkbox"/> Opening 3 parts <input type="checkbox"/> Opening 1 part <input type="checkbox"/> Wood Floor <input type="checkbox"/> Steel Floor <input type="checkbox"/>	(Tick as appropriate)



EXPLANATION OF MARKING	
A : Scratch	H : Hole
U : Dent	XX : Replaced
B : Bend	P : Painted
W : Wave	M : Marking of Letter of make removed
S : Rust	L : Letter of make remaining
C : Corrode	
T : Tear	

SIZE OF DENT AND SCRATCH	
1 : Slight,	2 : Small,
3 : Medium,	4 : Large,
5 : Heavy	

DAMAGE TO CHASSIS	
YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
Severe <input type="checkbox"/>	Moderate <input checked="" type="checkbox"/>
Light <input type="checkbox"/>	

Name: Prosper Sugai  
 Signature: *Prosper Sugai*

Date of Issue: 2022/02/17  
 Designation: Director



**EAA COMPANY LIMITED**







# Vehicle Inspection Sheet 2

TYRES		CONDITION OF INTERIOR AND SEATS	
Steel Wheel	<input checked="" type="checkbox"/>	1.Smell of Tobacco	<input type="checkbox"/>
Alloy Wheel	<input type="checkbox"/>	2.Smell of Pet	<input type="checkbox"/>
Size of Tyre	<input checked="" type="checkbox"/>	3.Presence of Nicotine	<input type="checkbox"/>
	185/60R15	4.Presence of Hair	<input type="checkbox"/>

CONDITION OF				CONDITION OF ROOM CLEANING		
1.Engine	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	1.Clean	<input checked="" type="checkbox"/>
* (a)Smoke Emission	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	2.Medium	<input type="checkbox"/>
(b)Other functions	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	3.Dirty	<input type="checkbox"/>
2.Muffler	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>		
3.Transmission	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>		
4.Battery	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>		
5.Electrical Instruments	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>		

\*To confirm whether the smoke emission of the vehicle is in conformity with the appropriate Japanese/European Standards, or in the case of a diesel driven motor vehicle, it has a maximum opacity of 50 per cent

CONDITION OF ACCESSORIES						
Air-conditioner (Single <input checked="" type="checkbox"/> Dual <input type="checkbox"/> )	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	Sliding Roof (Power <input type="checkbox"/> Manual <input type="checkbox"/> )	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
Power Steering	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	Jack	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
Power Window (1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input checked="" type="checkbox"/> )	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	Wrench	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
Electrical central Locking	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	ABS	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
Power Mirrors (Door <input checked="" type="checkbox"/> Fender <input type="checkbox"/> )	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Rear Wiper	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
Keyless entry and start	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Rear Spoiler	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
Audio switch on	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	High Mount Rear Stop Lamp	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
AM/FM Radio	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Bumpers (Coloured <input checked="" type="checkbox"/> Black <input type="checkbox"/> )	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
Cassette	Fixed	<input type="checkbox"/>	None	<input checked="" type="checkbox"/>	Door Visor (1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input checked="" type="checkbox"/> )	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
CD Player	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Mud Guard (Coloured <input type="checkbox"/> Black <input type="checkbox"/> )	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
TV	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Wheel Cover (1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input checked="" type="checkbox"/> )	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
GPS Navigation System	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Side Slide Glass (Cut Glass)	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
SRS Air Bag (Single <input type="checkbox"/> Dual <input checked="" type="checkbox"/> )	Fixed	<input checked="" type="checkbox"/>	Fixed	<input type="checkbox"/>	Roof Rails	Fixed <input checked="" type="checkbox"/> None <input type="checkbox"/>
Air Pure Filter	Fixed	<input type="checkbox"/>	None	<input checked="" type="checkbox"/>	Front Grill Guard (Large <input type="checkbox"/> Small <input type="checkbox"/> )	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
Rear Speaker (Single <input type="checkbox"/> Dual <input checked="" type="checkbox"/> )	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Side Steps	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
Floor Mat (1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input checked="" type="checkbox"/> )	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Roller Bar	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
Leather Seats	Fixed	<input type="checkbox"/>	None	<input checked="" type="checkbox"/>	Rear Cargo Bed Cover	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
Radio Antenna (Power <input type="checkbox"/> Manual <input checked="" type="checkbox"/> )	Good	<input checked="" type="checkbox"/>	Bad	<input type="checkbox"/>	Rear Protect Bar	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>
Front Fog Lamp (Single <input type="checkbox"/> Dual <input checked="" type="checkbox"/> )	Fixed	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Rear Spara Tyre Cover	Fixed <input type="checkbox"/> None <input checked="" type="checkbox"/>

(Tick as appropriate)

Name: Prosper Sugai

Date of Issue: 2022/02/17

Signature:

Designation: Director



**EAA COMPANY LIMITED**





Certification Number  
Chassis Number

VE-2202-002-001  
NSP170-7256696



PIONEER OF PRE-EXPORT INSPECTION